

ADDITIONAL COMMENTS

SOME FLASHING'S ARE LIFTED - NEED GLUE.

Roof: NOT ALL HIP AND RIDGE TILES ARE GIVED DOWN. CRACKED MORTAR CAP'S. SEVERAL SLIDING TILES AT FRONT HIP'S. GAS VENT PIPES HAVE NO RAIN COLLAR'S. (2) VENT PIPES ON WEST SIDE HAVE FLASHING'S IMPROPERLY FOLDED INTO PIPES. PATIO COVER IS LIFTING ALONG DRIP EDGE. (Roof Need's SPOT REPAIR'S)

NOTE: IRRIGATION VALVES IN REAR YARD SHOW SPOT LEAKAGE - REPAIR. SYSTEM APPEAR'S NOT IN OPERATION - DRY GRASS ETC. - VERIFY OPERATION @ FINAL WALK.

RECEIPT

Date: 4/22/03 Inspection #

Name: [REDACTED]

Address: [REDACTED]

Inspection: \$ [REDACTED] Paid by Invoice Check # MAIL Cash Credit Card Escrow

Other\*\*: \$ [REDACTED] \*\*Other: Radon DILHR Pool/spa NO

Total: \$ 235 - Well & Septic Pest

Inspected by: G Swintek 480-628-5220